



TeSuCon

Technical Support & Consultancy

REPORT TURBINE INSPECTION
SN 15401275, WINDPARK SLUFTER WEST 9



Report No. GE15002015009

20-11-2015

CONFIDENTIAL – Distribution to 3rd parties strictly prohibited

Contents

1 Purpose 3

2 Abbreviations..... 3

3 General information 4

4 Wind turbine main components 4

5 Documents..... 5

6 Logbook: Overview of recent maintenance 6

7 Logbook: Notable events 6

8 Tower and towerbase 7

9 Yaw system 8

10 Nacelle 9

11 Hydraulic system and brake 10


12 Gearbox and main shaft 10


13 Generator and coupling 12

14 Hub..... 13

15 Rotor blades 17

16 Conclusion..... 18



| | | | |
|---|---|--------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 2 of 18 | |

1 Purpose


On behalf of Vattenfall an inspection has been executed on the wind turbine. The purpose of the inspection is to determine the technical state of the wind turbine.

2 Abbreviations

| | |
|------------|-------------------------|
| ok | okay |
| nok | not okay |
| na | not applicable |
| nav | not available |
| nc | not checked |
| info | for information purpose |

Items marked with "ok" and "info" show no visual irregularities. All issues which are not acceptable are marked with "**nok**". Items which are "**nok**" will be classified in three different classes.

| Class | Clarification | Description in report |
|---------------|---|------------------------------|
| Priority Low | An irregularity, which is not a safety issue, and is relatively easy to solve. | <i>Low</i> |
| Priority High | An irregularity, which is not a safety issue, and is more serious and is more time and/or money consuming to solve. | <i>High</i> |
| Safety Issue | Issues which concern the safety of the people working in the turbine. | <i>Safe</i> |


| | | |
|--|---|--------------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | 15401275 |
| | Date: 20-11-2015 | Page 3 of 18 |

3 General information

| | |
|-----------------------|-------------------------------|
| Wind turbine name: | Windpark Slufter West 9 |
| Wind turbine type: | GE1.5S |
| Wind turbine S/N: | 15401275 |
| Location: | Rotterdam-Maasvlakte, NL |
| Hub height: | 65 |
| Nominal power [kW]: | 1500 |
| Year of installation: | 2003 |
| Date of inspection: | 20-10-2015 |
| Inspectors: | D. Lagerweij J. Langenbach |


4 Wind turbine main components

| Component | Type | Year | Serial number |
|------------------|---|------|--------------------|
| Convertor | GE Power Convertor 151X1228KA02SA01 | - | EW001 VIA |
| Gearbox | Winergy PEAS 4390,2 | - | 4801084 - 0020 - 3 |
| Revision gearbox | - | - | - |
| Gearbox oil | Castrol Optigear Syn A320 <i>(according to label in towerbase)</i> | 2009 | - |
| Generator | Winergy JFEA-500SR-04A | 2003 | 5133497 |
| Blade 1 | GE Rotor Blades | - | 2363 |
| Blade 2 | GE Rotor Blades | - | 2455 |
| Blade 3 | GE Rotor Blades | - | 2448 |

| | | | |
|--|---|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 4 of 18 | |

5 Documents

| | Component | Remark | |
|---|--------------------|--|-----|
| 1 | Operator manual | <p>Operating manual is available at the turbine.</p> <p>Machine directive 2006/45/EC, 1.7.4.2 states as part of the Contents of instructions:</p> <p><i>"(e) the drawings, diagrams, descriptions and explanations necessary for the use, maintenance and repair of the machinery and for checking its correct functioning;"</i></p> | ok |
| 2 | Wiring diagram | <p>Wiring diagrams are not available at the turbine.</p> <p>Machine directive 2006/45/EC, 1.7.4.2 states as part of the Contents of instructions:</p> <p><i>"(e) the drawings, diagrams, descriptions and explanations necessary for the use, maintenance and repair of the machinery and for checking its correct functioning;"</i></p> | ok |
| 3 | Hydraulic diagram | <p>Hydraulic diagrams are not available at the turbine.</p> <p>Machine directive 2006/45/EC, 1.7.4.2 states as part of the Contents of instructions:</p> <p><i>"(e) the drawings, diagrams, descriptions and explanations necessary for the use, maintenance and repair of the machinery and for checking its correct functioning;"</i></p> | nok |
| 4 | Maintenance manual | <p>Maintenance manual is not available at the turbine.</p> <p>Machine directive 2006/45/EC, 1.7.4.2 states as part of the Contents of instructions:</p> <p><i>"(e) the drawings, diagrams, descriptions and explanations necessary for the use, maintenance and repair of the machinery and for checking its correct functioning;"</i></p> | nok |
| 5 | Logbook | Logbook is available at the turbine. | ok |


| | | | |
|---|---|--------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 5 of 18 | |


6 Logbook: Overview of recent maintenance

| Year | Type of maintenance | Date of execution | Maintenance schedule |
|------|---------------------|-------------------|----------------------|
| | Commissioning | 09-2003 | 2003 |
| ... | ... | ... | ... |
| 9 | 1 year service | 28-11-2012 | 2012 |
| 9½ | ½ year service | 12-03-2013 | |
| 10 | 1 year service | 26-09-2013 | 2013 |
| 10½ | ½ year service | 29-04-2014 | |
| 11 | 1 year service | 10-12-2014 | 2014 |
| 11½ | ½ year service | 22-05-2015 | |
| 12 | 1 year service | 14-10-2015 | 2015 |





7 Logbook: Notable events


| Date | Event |
|------------|-----------------------|
| 31-10-2008 | Exchanged coupling |
| 09-01-2011 | Slip ring exchanged |
| 11-12-2012 | Slip ring exchanged |
| 04-09-2014 | HSS bearings replaced |






| | | |
|---|---|--------------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | 15401275 |
| | Date: 20-11-2015 | Page 6 of 18 |


8 Tower and towerbase

| | Item | Remark | |
|---|---------------------|---|--|
| 1 | Tower outside | Light at the outside is broken and has damaged the paint of the tower.  |  Low |
| 2 | Controller overview |  | Info |
| 3 | Tower inside |  | Info |
| 4 | Miscellaneous | | ok |






| | | | |
|--|---|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 7 of 18 | |


9 Yaw system


| | Item | Remark | |
|---|----------------|--|--|
| 1 | Yaw section | | ok |
| 2 | Yaw ring teeth | Yaw ring shows no irregularities.  | ok |
| 3 | Yaw pinions | Yaw pinions show no irregularities.  | ok |
| 4 | Yaw gears | Paint work of the gears is not acceptable.  | <div style="color: red; font-weight: bold;">nok</div> Low |

| | | | |
|--|---|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 8 of 18 | |

10 Nacelle

| | Item | Remark | |
|---|---------------------|---|---|
| 1 | Nacelle overview |  | Info |
| 2 | Frame | Turbine is equipped with a cast-iron frame. | Info |
| 3 | Nacelle housing | <p>Parts of the insulation are damaged. Bolts of the nacelle frame are corroded (2nd picture).</p>  | <div style="text-align: center;">  Low </div> |
| 4 | Weather station |  | Info |
| 5 | Controller overview |  | Info |


| | | | |
|---|---|--------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 9 of 18 | |


| | | | | |
|---|---------------|--|---|-------------------|
| 6 | Miscellaneous | Corrosion at the housing of the GX2-box. |  | nok Low |
|---|---------------|--|---|-------------------|







11 Hydraulic system and brake


| Item | Remark | |
|------|---------------|---|
| 1 | Overview |  Info |
| 2 | Leakage | ok |
| 3 | Miscellaneous | ok |

12 Gearbox and main shaft



| Item | Remark | |
|------|--|---|
| 1 | Main shaft bearings Grease of the main bearing is not magnetic. |   ok |

| | | |
|---|---|---------------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | 15401275 |
| | Date: 20-11-2015 | Page 10 of 18 |


| | | | |
|---|-------------------|---|------------------------------|
| 2 | Radiators |  | <i>Info</i> |
| 3 | CCJ-unit | No CCJ-filter present in the turbine. | <i>Info</i> |
| 4 | Gear oil system | Oil leakage present at the gear oil system.     | not ok <i>High</i> |
| 5 | Hoses and pipes | | ok |
| 6 | Paint / Corrosion | | ok |
| 7 | General leakage | | ok |
| 8 | Slip ring for hub |  | <i>Info</i> |

| | | |
|--|---|---------------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | 15401275 |
| | Date: 20-11-2015 | Page 11 of 18 |

13 Generator and coupling


| | Item | Remark | |
|---|-------------------|---|------|
| 1 | Coupling | <p>The coupling shows no irregularities.</p>  | ok |
| 2 | Paint / Corrosion | | ok |
| 3 | Slip ring | <p>The slip ring shows no visual irregularities.</p>  | Info |






| | | | |
|---|---|---------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 12 of 18 | |

14 Hub


| | Item | Remark | |
|---|----------------------|---|----------------------------|
| 1 | Blade bearing | <p>Several caps of the nuts of the bearing show small cracks.</p>  | <p>Info Low</p> |
| 2 | Overview inside | <p>In general, the hub is clean and there is no excessive corrosion present.</p>  | <p>ok</p> |
| 3 | Hub cabinet overview |  | <p>Info</p> |
| 4 | Boxes blade 1 | <p>Control box and battery box show no irregularities.</p>  | <p>ok</p> |





| | | | |
|---|---|---------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 13 of 18 | |


| | | | |
|---|---------------|---|---------------------------|
| 5 | Boxes blade 2 | <p>Small loose parts of the fuses are visible behind the glass cover (2nd picture). Bolt connection of the cover of the battery box is broken (4th picture).</p>  | <p>NO Low</p> |
| 6 | Boxes blade 3 | <p>Cover of the fuse is missing (1st and 2nd picture).</p>  | <p>NO High</p> |

| | | | |
|---|---|---------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 14 of 18 | |

| | | | |
|---|----------------------------------|---|----------------------------|
| 7 | Mounting of the electrical boxes | <p>The mounting of the boxes shows no irregularities.</p>  | ok |
| 8 | Pinions of pitch gears | <p>Wear on one tooth of the pinions of the pitch gears.</p>  | <p>not High</p> |
| 9 | Pitch teeth at zero of blade 1 | <p>The tooth at zero shows wear.</p>  | <p>not High</p> |


| | | | |
|---|---|---------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 15 of 18 | |

| | | | |
|----|--------------------------------|--|----------------------------|
| 11 | Pitch teeth at zero of blade 2 | <p>The tooth at zero shows wear.</p>  | <p>nok High</p> |
| 12 | Pitch teeth at zero of blade 3 | <p>The tooth at zero shows wear.</p>  | <p>nok High</p> |
| 13 | Grease system pitch teeth | <p>There is an automatic grease system present in the hub. The system is not operational.</p>  | <p>nok High</p> |
| 14 | Pitch gears | <p>Some corrosion visible at the base of the pitch gears.</p>  | <p>nok Low</p> |
| 15 | Miscellaneous | | <p>ok</p> |

| | | | |
|---|---|---------------|----------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 16 of 18 | |

15 Rotor blades

| | | | |
|---|--------|---|------|
| 1 | Blades | <p>Repaired parts are visible on the leading edges of the blades.</p>  | Info |
|---|--------|---|------|

| | | |
|---|---|---------------|
|  <p>TeSuCon Technical Support & Consultancy</p> | Wind turbine inspection Windpark Slufter West 9 | 15401275 |
| | Date: 20-11-2015 | Page 17 of 18 |

16 Conclusion

The logbook shows that the turbine has been maintained on a regular basis, according to the maintenance schedule of GE.

The original gearbox and generator are present in the turbine. The high speed shaft bearings of the gearbox have been replaced in 2014.

The blades have been maintained recently.

The wear of the zero-tooth of the pitch ring is serious, but it is possible to solve this problem by assigning another tooth to be the zero-tooth. Dismounting and remounting of the blades is necessary to achieve this. The same thing can be done with the pinions, although replacing the pitch gears (with the pinions) is also an option.


The overall condition of the turbine is quite acceptable for a twelve year old turbine. There are however several issues (marked as **red** in this report) present and it is recommended to solve these, in order to improve the condition of the turbine.



D. Lagerweij

20-11-2015

TeSuCon B.V.
Mercuriusweg 8
3771NC Barneveld
+31610032858
dl@tesucon.nl
www.tesucon.nl


| | | | |
|--|---|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Wind turbine inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 20-11-2015 | Page 18 of 18 | |



TeSuCon

Technical Support & Consultancy

REPORT GEARBOX INSPECTION
SN 15401275, WINDPARK SLUFTER WEST 9



Report no. GE15002015019

24-11-2015

CONFIDENTIAL – Distribution to 3rd parties strictly prohibited

Contents

1. Purpose 3

2. General Information 3

3. Reporting setup 4

4. Inspection results 5

5. Summary 16

6. Conclusion 16



| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 2 of 16 | |


1. Purpose

On behalf of Vattenfall an inspection has been executed on the wind turbine gearbox. The purpose of the inspection is to determine the technical state of the gearbox. The visual inspection of the gearbox has been executed with a GE Everest XLG3 Videoscoop.

2. General Information


| Turbine Information | |
|----------------------------|-------------------------------|
| Wind turbine name: | Windpark Slufter West 9 |
| Wind turbine type: | GE1.5S |
| Wind turbine serial no: | 15401275 |
| Location: | Rotterdam-Maasvlakte, NL |
| Hub height: | 65 |
| Nominal power [kW]: | 1500 |
| Year of installation: | 2003 |
| Date of inspection: | 20-10-2015 |
| Inspectors: | D. Lagerweij J. Langenbach |

| Gearbox Information | |
|----------------------------|---|
| Gearbox type: | Winergy PEAS 4390,2 <i>i = 90,302</i> |
| Gearbox serial number: | 4801084 - 0020 - 3 |
| Production year gearbox: | - |
| Revision: | - |
| Revision number: | - |
| Oil type: | Castrol Optigear Syn A320 <i>(according to label in towerbase)</i> |
| Date of last oil change: | 2009 |

| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 3 of 16 | |


3. Reporting setup

The next drawing shows a cross-section of a planetary gearbox with two linear stages with corresponding bearing positions. The drawing should be used as a reference for the bearing position only.



| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 4 of 16 | |

4. Inspection results



Picture 1


Picture 1 shows bearing position no. 1, the bearing of the planet carrier at rotor side. No irregularities.



Picture 2

Picture 2 shows the bearing of the first planet wheel. No irregularities.

| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 5 of 16 | |



Picture 3


Picture 3 shows the bearing of the second planet wheel. No irregularities.



Picture 4

Picture 4 shows the bearing of the third planet wheel. No irregularities.

| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 6 of 16 | |



Picture 5

Picture 5 shows bearing position no. 5, the bearing of the planet carrier at generator side. The bearing shows no irregularities.



Picture 6

Picture 6 shows bearing position no. 6, the bearing of the low speed shaft at rotor side. The bearing shows no irregularities.

| | | | |
|--|--|--|--------------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | | Page 7 of 16 |



Picture 7

Picture 7 shows bearing position no. 7, the bearing of the low speed shaft at generator side. Two very small indentations visible at the raceway.



Picture 8

Picture 8 shows bearing position no. 8, the bearing of the intermediate shaft at rotor side. The bearing shows no irregularities.

| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 8 of 16 | |



Picture 9

Picture 9 shows bearing position no. 9, the bearing of the intermediate shaft at generator side. The bearing shows no irregularities.



Picture 10


Picture 10 shows bearing position no. 10, the bearing of the high speed shaft at rotor side. The bearing shows no irregularities.

| | | | |
|--|--|--------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 9 of 16 | |



Picture 11


Picture 11 shows bearing position no. 11, the radial bearing of the high speed shaft at generator side. The bearing shows no irregularities.



Picture 12

Picture 12 shows bearing position no. 11, the axial bearing of the high speed shaft at generator side. The bearing shows no irregularities.

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 10 of 16 | |




Picture 13

Picture 13 shows the active flank of the ring gear. No irregularities.



Picture 14

Picture 14 shows one of the planet wheels. None of the planet wheels show irregularities.

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 11 of 16 | |



Picture 15


Picture 15 shows the active flanks of the sun pinion. Stabilized micropitting visible at the flank.



Picture 16


Picture 16 shows the active flanks of the wheel of the low speed shaft in the linear stage. No irregularities.

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 12 of 16 | |



Picture 17


Picture 17 shows the active flanks of the pinion of the intermediate shaft in the linear stage. No irregularities.



Picture 18

Picture 18 shows the active flanks of the wheel of the intermediate shaft in the linear stage. No irregularities.

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 13 of 16 | |



Picture 19

Picture 19 shows the active flanks of the pinion of the high speed shaft in the linear stage. No irregularities.



Picture 20


Picture 20 shows the oil level of the gearbox. The oil level is a bit too low.

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 14 of 16 | |



Picture 21

The inside and bottom of the gearbox have been searched with a magnet. The magnet shows no steel particles.



| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 15 of 16 | |

5. Summary

The bearing of the low speed shaft at generator side shows two very small indentations at the raceway.

The active flanks of the sun pinion show stabilized micropitting.

No irregularities were found at the other inspected bearings and gears.

The oil level is a bit too low and no steel particles were found in the gearbox.

6. Conclusion

The condition of the gearbox is acceptable.


The small indentations on the bearing of the low speed shaft have probably been caused by particles from the damaged high speed bearings in 2014.

The oil level is a bit too low and it is recommended to fill up the gearbox at the next maintenance.

Dennis Lagerweij

Barneveld, 24-11-2015

TeSuCon B.V.
Mercuriusweg 8
3771NC Barneveld
The Netherlands
Tel +31610032858
Email dl@tesucon.nl
Web www.tesucon.nl

| | | | |
|--|--|---------------|----------|
|  TeSuCon Technical Support & Consultancy | Gearbox inspection Windpark Slufter West 9 | | 15401275 |
| | Date: 24-11-2015 | Page 16 of 16 | |